# MAC motor<sup>®</sup> - Integrated Servo Motor



# A new way of saving money All Electronics Inside

Brushless servo motors with integrated controller





# Save Money and Troubles

In the past building up a motion control system was a complicated affair involving many componets:

- PLC
- Indexer/controller
- Driver
- Motor with Encoder and Hall sensor
- A lot of cabelling to connect all these items

-and finally complicated software that had to be programmed properly

It required a lot of expertise to make the system function and the installation was very time consuming and involved many sources that could create faults. Electrical noise from the cables carrying the high motor currents added to the problems.

JVL has reduced these problems to a minimum by introducing of the Integrated MAC motor on the motion control market.

#### Previous system build-up



TT2124GB

In these motors the Indexer/controller, Driver. Encoder and Hall sensor are all built-in into one compact unit.

A software package, MacTalk, makes set-up extremely easy and expansion modules mounts directly into the motorhousing to adapt the motor to almost any application.

By investing in a modern integrated MAC motor from JVL you achieve the following benefits:

- Reduced material costs. Because the drive and controller are in the motor, most cabling to a control panel is eliminated
- Reduced labor costs With cabling eliminated, assembly time is greatly reduced
- Better quality and reliability
- Fewer connections, less wiring



- Ease of serviceability Because all electronics are selfcontained you simply change the motor
- Double supply facility to ensure that position and parameters are maintained after emergency stop
- Switching noise from the drive due to commutation is contained in the motor
- Reduced setup time 6th order digital filter requires only one tuning parameter for load or reflected inertia
- OEM cost savings, the modular approach means you only pay for the functionality required



### The major advantages of the MAC motors are:

- High performance
- Cost effective
- Decentral intelligence
- Quiet and maintenance free operation
- High efficiency
- Low operational cost
- Less machine space required
- Low installation cost. Shorter and faster installation
- Fewer possibilities for wiring errors
- Minimum positioning error during operation and halt
- Modular flexibility
- New users can easily set up the system

### Main features

- (basic MAC models) • Ideal for high volume applications in harsh industrial environments
- Accepts position and velocity commands sent via 2 serial interfaces
- Genuine AC-servomotor with high toque at high speed
- Pulse and direction input makes it possible to replace any step motor
- Quadrature output to master controller when used as a  $\pm 10V$ driver
- Switching technology in motor and power supplies
- High performance serial protocol with addressing facilities
- Easy and simple Windows program available for installation/ set-up



### The comple range of MAC motors<sup>®</sup>

The complete range of JVL AC servo, integrated MAC motors offer you a wide selection of motor sizes adaptable to a wide range of applications Cables

customers

Cables for all types of set up can be

delivered as required. In this way

installation is fast and easy for our

# The MAC motor - 50 to 134 W - the complete motion solution for smaller powers ratings

Brushless servo motor with integrated controller everything in one unit, except power supply.



Optionally an electronic brake, type

motors with a NEMA23 flange and

6.35mm shaft. It is usefull for hold-

ing the motor shaft fixed at power

off or when the motor is used in a

vertical application

MAB23x, can be mounted on all

IP67 versions can also be delivered. They are resistant against rough chemicals and ideal for use in food processing, pharmaceutical and chemical industries. A double shaft seal and leak-proof cable entry provide watertight sealing

JVL can supply a wide range of power supplies for supplying one or several MAC motors. They range from very simple do-it-yourself kits to big switch mode supplies. It should be noted that MAC800 includes a complete 115/230 VAC power supply for driver voltage. Only 24VDC for control circuit is required externally

# Adapt your motor to your application

The JVL Integrated motors utilizes the unique module concept. Plug-in expansion modules adapt the motor to the application. You can choose connector type, D-Sub, cable glands or M12 connectors and you can choose freely between Profibus, DeviceNet, CANopen or nano PLC control. A High

#### **Basic Modules**



MAC00-CS Low cost module, with cable glands. Pulse/dir. ±10V and 5V serial

**Pulse/Dir** Analog





MAC00-B1, General purpose module withSub-D connectors: Pulse/Dir, ±10V,







MAC00-B2 General purpose module RS 232 w/Cable Glands: otherwise same as -B1







MAC00-B4 General purpose module w/M12 connectors. Double supply







MAC00-B41 Is a MAC00-B4 module with extendeed I/O functions and USB



**Programable Modules** 





MAC00-R1 Nano-PLC Module w/Sub-D connectors: Stand-alone operation with 8 DI + 4 DO

PLC NANO





MAC00-R4 Nano-PLC Module w/M12 connectors: otherwise same NANO as -R1



#### **Process Control Modules**



MAC00-P4 or P5 Process Control modul **PROCESS** with analogue 4-20mA Control input



DSUB 9 or 15-pin DSUB connectors IP42 Cable Shielded cable up to 20 m IP67 M12 M12 screw connector. Cable up to 20 m. IP67 upp. Position and parameters can be maintained under emergency stop



Speed and wireless modules add to the possibilities. This means that you have possibilities as with no other motors on the market, and also important, you only pay for what you need. Moreover, if you do not find the feature you need please contact us and we will develop a customized module for you.

#### Wireless Modules



Field Bus Modules



MAC00-FC4 CAN bus Module w/ M12 connectors: Bus, 4 DI/DO and RS232



MAC00-FD4 DeviceNet Module w/M12 connectors: DeviceNet<sup>2</sup> Bus, 4 DI/DO and RS232

MAC00-FP4 PROFI Profibus Module BŪŚ w/M12 connectors: Bus. 4 DI/DO and RS232



MAC00-EI4/EC4 EtherNET/IP / EtherCAT EtherNet/IP Module w/M12 connec- EtherCAT tors: Bus and RS232



MAC00-EP4 Profinet IO SERCOS MAC00-ES4 Sercos III MAC00-EM4 Modbus TCP MAC00-EL4 Powerlink POWERLINK

#### High Speed Multi-Axis modules









Analog ±10V for speed or torque control or 24V home switch Pulse I/O RS422 balanced inputs for pulse/direction incremental signal or encoder output

2 of the inputs can be used as negative or positive limit switch inputs. Limit +/-



Brushless servo motor with integrated controller everything in one unit including mains power supply

Solid aluminium housing which protects and shields the internal components

Standard Industry Servo flange and shaft

Ball bearings for maintenance free operation

Gears

A wide range of planetary, worm

and backlash free gears can be

provided for the MAC motors







For applications in which motor position must be maintained at power-off, or for use in vertical applications, the 400 and 750W MAC motors can be supplied with

RS232 and RS485 interface for setup and monitoring

Pulse input and outputs ±10V analogue input In position and Error output

> Expansion module (shown MAC00-xx) for adapting to a broad range of applications

Main Control board

High efficiency Power Mos-fets in motor driver Built-in 115/230 VAC mains power supply

Optical encoder (8000 CPR) for precise positioning and speed regulation. Optional: multifunction encoder



MAC1500 and MAC3000

Soon available. They will extend the

MAC motor power range to 3000 W.

Present series of expansion modules

will still fit in these larger motors

### MAC400

MAC400 for medium power ratings with incremental encoder or multiturn encoder for precise positioning and speed regulation



**Built-in Brake** 

3 phase

brushless servo motor







Material Handling Systems vertical and horizontal transfer movements



Slitting Machines. High speed traverse applications for slicing materials



Auto Handling. High speed pick and place movements



Profile Cutting Machines Intricate profile movements of water jets and laser cutters

#### Other applications

- Replacement for pneumatic solutions
- Replacement of step motors offering much faster response and speed
- Conveyor systems
- Printing machines
- 3-D and XY tables
- Replacement for frequency inverters
- ±10V speed/torque driver for external controllers
- Screw and toothed belt pick and place robots
- Labelling dispensers

# Software

JVL delivers the software that you need.

## MacTalk

For setup, monitoring and diagnotics Mac-Talk is the preferred choice for most users.

Although advanced functionality is included, all operations are very intuitive and easy to use.

MacTalk allows you to adjust all vital parameters and save them in a file- or load them from a file. It is also possible to monitor parameters and motor status in real time.

When commissioning a system MacTalk even provides a convenient way to test and adjust your system. You can easily set up a test sequence and then adjust parameters like velocity, acceleration and torque. It is possible to select the distance moved and the delay between the moves. The more advanced 6th-order filter used in MAC motors, instead of a simple PID loop, is easily adjusted.

A nice feature is the Update function: if your PC is connected to the Internet you can update the MacTalk software itself - and even the servo system's firmware can be updated both the driver and the expansion module. Once bought, MacTalk will stay "fresh".

- always including the latest functionality.

## **Graphical Programming**

The Nano PLC MACOO-Rx module can be programmed from MacTalk using userfriendly, icon-based commands in a graphical programming environment. With 8 inputs 4 outputs, all 5-24VDC, and one ±10V analogue input, a small PLC system can be programmed. It is register-based with different kinds of relative or absolute movements, Jump and IF commands, timer and other functions. It is possible to request input conditions and set outputs.

🔉 MacTalk - N							
Ele View Motor	Offline M	AC00-RxP Setup	p Updates Help			_	
6 .			1 m	3	ی 🛃	TOP 💏 AI	
Open	Save			Reset motor Filt	er setup STOP	Motor COM scan	
Main Registers	Advanced	Filter parameter	s Tests Scope			Status	
Startup mode	-	Change actual mo	▼ Error handling			Motor status	
<ul> <li>Passive</li> <li>Velocity</li> </ul>	V 1	.nange actual moi		0	Counts	Actual mode Actual velocity	Passive 0 RPM
C Position			Position limit min	0	Counts	Actual position	0 Cou
C Gear C Gear(Follow)			Position limit max	0	Counts	Motor load (mean) Regenerative load	0 % 0 %
C Analogue ve			Error acceleration	0	RPM/S	Temperature	0 °C
C Analogue ve	locity (with de	eadband)				Bus voltage	0 Volt:
C Analogue ve C Velocity/ana			Cutput 1 (01) Use	r controlled		Control voltage	0 Volts
C Analogue tor	que (direct)		C Output 2 (02) Use			Velocity of input Analogue input AIN1	0 Cts/ 0.00 Volts
C Analogue ge	ar		Invert In position o			Analogue input AIN2	0.00 Volts
C Analogue bi-	position		Invert Error output	(U2) Seriel Data	•	VI/O management	
C Analogue to	position		Positive edge posi			MF1B MF1A MF2B MF2A AIN2 AIN2	
Profile data Max velocity	100 -	BE				MF2B MF2B	
Acceleration		_	PM/S Disable brake			AIN2	
	5003	<u> </u>	Analogue input onset	0.00	Volts	AIN ANINP	
S-Curve		Diff 🔄 💌				Errors	
Torque	300 🗄	-	Zero search mode	Disabled	-		
Load	1.0000	Ur	nit Use index after zer Zero search position	ro search -10000			
🗆 Invert motor di	rection				Counts		
			Zero search velocity	-50	RPM	Status	
			Zero search torque	100	%	Motor in position Motor acceleration	
			V Undervoltage hand			Motor deceleration	g er DC voltage lo
			Undervoltage -> S		an to passive	Supervision of po Mains AC voltage	
			Undervoltage -> S		go to postino	Driver stage disat	
			- Communication -		_	E	
			Motor address	254		<u> </u>	
		ACOO-RXP Setup		connection on COM			
6.	Offine M	4	Updates Help	3	چه و	EA 🕪 90	
Ele Yiew Motor	Qffine M Save	Save in flash	Ladates Hop	eset motor Fib		IMOTOR COM scan	
Ele Yiew Motor	Qffine M Save	Save in flash	Updates Help	eset motor Fib	چه و	EA 🕪 90	•
Ele View Motor Open - Main Registers	Qffine M Save	Save in flash	D Lodates Help Reset position Clear errors Tests Scope MACOOR	Reset motor Filte P EthernetIP	چه و	COM scan Status Actual mode	Passive
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offline Mi Save Advanced	Save in flash 1 Fiter parameters	Lodates Help     Learer errors     Tests Scope MACOURN     Learer Sp	Reset motor Filte P EthernetIP	er setup STOP	COM scan Status Actual mode Actual velocity Actual position	0 RPM 0 Cour
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offline Mi Save Advanced	Save in Flash 1 Filter parameters Stop 1: Set Mode	b Updates Heb Reset pation Clear errors a Tests Scope MACOORN Passe Sr e: Position	Reset motor Filt P Ethemetil P ngle St. Define	er setup STOP	Potor COM scan Status Motor status Actual mode Actual velocity Actual welocity Actual option Motor isoda (mean)	0 RPM 0 Cour 0 %
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offline Mi Save Advanced	Save in fiash 1 Filter parameters Stop 1: Set Mode 2: Move (AB	Lodates teb      Lodates teb      React position Clear errors      Tests Scope M4C00R	Reset motor Filt P Ethemetil P ngle St. Define	er setup STOP	OP COM scan Status Status Actual velocity Actual velocity Actual velocity Moter toda (mean) Regenerative load Temperature	0 RPM 0 Cour
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offline M Save Advanced mmable Start	Save in flash 1 Filter parameters Stop 1: Set Mode 2: Move (Al 3: Set output	Lodates Heb     Locates Heb     Locates Heb     Locates errors     Tests Scope MACOURA     Pause Sp e: Position     Position     too: 4000 Counts acc at 1 low	Reset motor Filt P Ethemetil P ngle St. Define	er setup STOP	COM scan     Status     CoM scan     Status     Actual velocity     Actual velocity     Actual velocity     Actual velocity     Actual velocity     Actual velocity     Teigenerative load     Temperature     Inputs	0 RPM 0 Cour 0 % 0 % 0 %
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offline Mi Save Advanced	Save In Flash 1 Filter parameters Stop 1: Set Mode 2: Move (AB 3: Set output 4: If (input 2:	Lindates Esto     Lindates Esto     Reset position     Tests Scope MACOURN     Passe SP     Position     Position     Position     Al Tow     high) jump to 2	Reset motor Filt P Ethemetil P ngle St. Define	er setup STOP	COM scan     Com scan     Status     Com scan     Status     Com scan     Com	0 RPM 0 Cour 0 % 0 % 0 % 0 % 0 % 0 %
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offline M Save Advanced mmable Start	Save in Flash 1 Filter parameters 1: Set Mode 2: Move (AB 3: Set output 4: If (input 2: 5: Wait 123-	Lodates Heb     Every Data     Texts Scope MACORP     Every MACORP     Every Sram     Position     s) - pos: 4000 Counts acc at I low     -high) jump to 2     Ans	Reset motor Filte P [EthernetilP] ngle St. Define c: 1000 RPM/s v	er setup STOP	COM scan	0 RPM 0 Cour 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 %
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offline M Save Advanced mmable Start	Seve in Flash I Filter parameters I: Set Mode 2: Move (Al 3: Set output 4: If (input 2: 5: Wait 123 6: Move (Al	Loddes Beb     Lette postion Close errors     Tette Scope M4C00R     Postion     Post	Reset notor Fib P EthemeilP mgle St. Define c: 1000 RPM/s v 000 RPM/s vel: 1	er setup STOP	Proc. COM scan     Add     Actual velocity     Actual velocit	0 RPM 0 Cour 0 % 0 % 0 % 0 % 0 Volts 0 Volts 0 Cts/% 0.00 Volts
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Qffine M Save Advanced mmable Start	Seve in Flash I Filter parameters I: Set Mode 2: Move (Al 3: Set output 4: If (input 2: 5: Wait 123 6: Move (Al 7: Set output	Lipdates Beb     Reset position Clear errors     Tests Scope MACOURN     Position     Position     Des) - pos: 4000 Counts acct     At low     high) jump to 2     4 ms     is) - pos: 0 Counts acct: 21     is (2 low and 3 high and 4	Reset notor Fib P EthemeilP mgle St. Define c: 1000 RPM/s v 000 RPM/s vel: 1	er setup STOP	COM scan	0 RPM 0 Cour 0 % 0 % 0 % 0 % 0 Volts 0 Volts 0 Cts/% 0.00 Volts
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offine M Save Advanced mmable Start	Sive in Rash 1 Filter parameter: 1: Set Mode 2: Move (Al 3: Set output 4: If (input 2: 5: Wait 123 5: Wait 123 5: Move (Al 7: Set output 8: Velocity	Lodates (beb      Reset position     Clear errors     Tests Scope MACOURs     Position     Position     Position     Position     Position     Toos: 4000 Counts acc     At Ilow     high) pimp to 2     Ams     position Counts acc:20     Ams         (Position Reg 1*123)	Reset notor Fib P EthemeilP mgle St. Define c: 1000 RPM/s v 000 RPM/s vel: 1	er setup STOP	COM scan	0 RPM 0 Cour 0 % 0 % 0 % 0 % 0 Volts 0 Volts 0 Cts/% 0.00 Volts
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offine M Save	Seve In Fash 1 Filter parameter Stop 1: Set Mode 2: Move (Al 3: Set output 4: If (input 2: 5: Wait 123 6: Move (Al 7: Set output 8: Velocity 9: Set posit	Loddes Beb     Learner postbol Clarge arrors     Tests Scope MACOURP     Learner     Learner MACOURP     Learner MACOURP     Learner MACO	Reset notor Fib P EthemeilP mgle St. Define c: 1000 RPM/s v 000 RPM/s vel: 1	er setup STOP	COM scan	0 RPM 0 Cour 0 % 0 % 0 % 0 % 0 Volts 0 Volts 0 Cts/% 0.00 Volts
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offine M Save	Seve In Fash 1 Filter parameter Stop 1: Set Mode 2: Move (Al 3: Set output 4: If (input 2: 5: Wait 123 6: Move (Al 7: Set output 8: Velocity 9: Set posit	Lodates (beb      Reset position     Clear errors     Tests Scope MACOURs     Position     Position     Position     Position     Position     Toos: 4000 Counts acc     At Ilow     high) pimp to 2     Ams     position Counts acc:20     Ams         (Position Reg 1*123)	Reset notor Fib P EthemeilP mgle St. Define c: 1000 RPM/s v 000 RPM/s vel: 1	er setup STOP	COM scale	0 RPM 0 Cour 0 % 0 % 0 % 0 % 0 Volts 0 Volts 0 Cts/% 0.00 Volts
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offine M Save	Seve In Fash 1 Filter parameter Stop 1: Set Mode 2: Move (Al 3: Set output 4: If (input 2: 5: Wait 123 6: Move (Al 7: Set output 8: Velocity 9: Set posit	Lodates Beb      Resc position Clear errors      Tests Scope MACOORs      Position     Posi	Reset notor Fib P EthemeilP mgle St. Define c: 1000 RPM/s v 000 RPM/s vel: 1	er setup STOP	COM scan	0 RPM 0 Cour 0 % 0 % 0 % 0 % 0 Volts 0 Volts 0 Cts/% 0.00 Volts
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offine M Save Save Save	Seve In Flash 1 Filter parameter: Store 1: Set Mode 2: Move (Al 3: Set output 4: If (input 2: 5: Wait 123 6: Move (Al 7: Set output 8: Velocity: 9: Set positi 10: Zero see 11: Set Torq	Lodates Beb      Resc position Clear errors      Tests Scope MACOORs      Position     Posi	Paster notor Fib Presentation (P) Provide the second of th	vuer registers vuer registers	COM scale	0 RPM 0 Cour 0 % 0 % 0 % 0 % 0 Volts 0 Volts 0 Cts/% 0.00 Volts
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offine M Save	Seve In Flash 1 Filter parameter: Store 1: Set Mode 2: Move (Al 3: Set output 4: If (input 2: 5: Wait 123 6: Move (Al 7: Set output 8: Velocity: 9: Set positi 10: Zero see 11: Set Torq	Loddates Beb     Learer position     Clear ensurement     Tests Scope MACOURP     Learer     Sono MACOURP     Learer     Sono MACOURP     Learer     Sono MACOURP     Learer     Sono MacOurts acc     At low     High jump to 2     Ams     bs)- pos: 0 Counts acc: 20     Ams     bs)- pos: 0 Counts acc: 20     count	Paster notor Fib Presentation (P) Provide the second of th	vuer registers vuer registers	COM scale     COM scale     COM scale     COM scale     COM scale     COM scale     Common scale     Co	0 RPM 0 Cour 0 % 0 % 0 % 0 % 0 Volts 0 Volts 0 Cts/% 0.00 Volts
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offine M Save Save Save	Steep Infacts 1 Filter parameters Steep 1: Set Mode 2: Move (Al 3: Set output 4: If (input 2: 5: Wait 123 6: Move (Al 7: Set output 9: Set posit 10: Zero see 11: Set Torq 12: Move (Al 13: Set output 13: Set output	Loddates Beb     Learer position     Clear ensurement     Tests Scope MACOURP     Learer     Sono MACOURP     Learer     Sono MACOURP     Learer     Sono MACOURP     Learer     Sono MacOurts acc     At low     High jump to 2     Ams     bs)- pos: 0 Counts acc: 20     Ams     bs)- pos: 0 Counts acc: 20     count	Paster notor Fib Presentation (P) Provide the second of th	vuer registers vuer registers	COM scale     COM scale     COM scale     COM scale     COM scale     COM scale     Common scale     Co	0 RPM 0 Cour 0 % 0 % 0 % 0 % 0 Volts 0 Volts 0 Cts/% 0.00 Volts
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offine M Save	Steep Infacts 1 Filter parameters Steep 1: Set Mode 2: Move (Al 3: Set output 4: If (input 2: 5: Wait 123 6: Move (Al 7: Set output 9: Set posit 10: Zero see 11: Set Torq 12: Move (Al 13: Set output 13: Set output	Lidates Eleb      Rescipcion Clast errors     Tests Scope MACOURN     Paure Sy e. Position     Paure Sy e. Position     Al low -high) jump to 2     4 ms     be) - pos: 0 Counts acct 21     4 ms     to 2 low and 3 high and 4     (Position Reg 1 * 123)     ion to 1234 Counts     ue to 12 %     obj - pos: 0 Counts acct 20     at Blow     input 5-rising edge	Paster notor Fib Presentation (P) Provide the second of th	vuer registers vuer registers	COM scale     COM scale     COM scale     COM scale     COM scale     COM scale     Common scale     Co	0 RPM 0 Cour 0 % 0 % 0 % 0 % 0 Volts 0 Volts 0 Cts/% 0.00 Volts
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offine M Save	Seven hindh 11 Filter parameter Store 1: Set Mode 2: Move (Al 3: Set output 4: If (input 2: 5: Wait 123 6: Move (Al 7: Set output 10: Zerro see 11: Set Tong 12: Move (Al 13: Set output 13: Set output 13: Set output 14: Wait will 15: Set Mode	Lodates Beb     Leare position     Clear entrors     Tests Scope MACOOR     Leare MACOOR     Leare Scope MACOOR     Leare MACOOR	Paster notor Fib Presentation (P) Provide the second of th	vuer registers vuer registers	COM scale     COM scale     COM scale     COM scale     COM scale     COM scale     Common scale     Co	0 RPM 0 Cour 0 % 0 % 0 % 0 % 0 Volts 0 Volts 0 Cts/% 0.00 Volts
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offine M Save	File parameter Step Prints 1: Set Mode 2: Move (4) 3: Set output 4: If (mput 2: 5: Wait 123: 6: Move (4) 7: Set output 10: Zero see 11: Set Torrg 12: Move (4) 13: Set output 14: Wait until 15: Set Mode 16: Wait 123:	Loddes Beb     Loddes Beb     Loddes Beb     Lots Front     Lots     Lots Front     Lots     Lots	Paster notor Fib Presentation (P) Provide the second of th	vuer registers vuer registers	CCM scan     CCM scan     CCM scan     CCM scan     CCM scan     Actual velocity	0 RPM 0 Cour 0 % 0 % 0 % 0 % 0 Volts 0 Volts 0 Cts/% 0.00 Volts
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offine M Save mable Start	Several Andre 1 Filter parameters Several Andre 2 Several Andr		Paret not PR P Etherael P c 1000 RPM/s vet 1 1000 RPM/s vet 1 1000 RPM/s vet 1	vuer registers vel: 2000 RPM	Construction  C	0 RPM 0 Con 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 %
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offine M Save mable Start	Presentation     P	Lodates Beb     Learner position     Learner MACOURP     Learner     Lear	Paret not PR P Etherael P c 1000 RPM/s vet 1 1000 RPM/s vet 1 1000 RPM/s vet 1	vuer registers vel: 2000 RPM	Construction  C	0 RPM 0 Con 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 %
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offine M Save mable Start	File parameters Sieve in floot 1 File parameters Sieve in floot 1 Sieve in floot 2 Sieve in floot	Lodates Beb     Learner position     Learner MACOURP     Learner     Lear	Paret not PR P Etherael P c 1000 RPM/s vet 1 1000 RPM/s vet 1 1000 RPM/s vet 1	vuer registers vel: 2000 RPM	Constant and a c	0 RPM 0 Coru 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 %
Ele Yiew Motor Open Main Registers MACOO-Rx Progra	Offine M Save mable Start	See inflost         See inflost           Filter parameters         Step           1: Set Mode         Step           2: Move (Al)         Step output           4: fir(mpu12)         Step output           5: Wart 123         Step output           9: Velocity-         Step output           10: Zero see         11: Set Tourg           11: Set Tourg         12: Move (Al)           13: Set output         14: Weak until           15: Set Mode         16: Weak 123           16: FastMACC         18: FastMACC	Lodates Beb     Learner position     Learner MACOURP     Learner     Lear	Paret not PR P Etherael P c 1000 RPM/s vet 1 1000 RPM/s vet 1 1000 RPM/s vet 1	vuer registers vel: 2000 RPM	Corti Suali and      Actual velocity     Andogue republic     Bur velocity     Andogue republic     Welocity of riput     Andogue republic     METB     Marcia     Advance     Allin P     Encore     Status     Actual velocity     Advance	0 RPM 0 Coru 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 % 0 %

All register and parameters in the MAC motor can be accessed and changed if required.

### OCX software

If your application is controlled by a PC you might prefer JVL's OCX software. The OCX (OLE Custom Controls - also known as ActiveX Controls) enables applications to be easily developed in for example:

- Visual Basic •
- Visual C++
- Visual .Net

• Delphi

- Borland C++ Builder
- LabView
- Excel

any other environment supporting OCX controls.



	<b>A</b>									
Technical specifications	MAC50	MAC95	MAC140	MAC141	MAC400-D2	MAC800-D2	MAC1500-D2	MAC3000-D2	Unit	
Supply voltage	12-48VDC	12-48VDC	12-48VDC	12-48VDC	115/230VAC	115/230VAC	3x400VAC	3x400VAC	VAC	
Speed range (nominal)	0-4000	0-4000	0-4000	0-2700	0-3000	0-3000	0-3000	0-3000	RPM	Г
Rated power@4000/3000 RPM	46/0.062	92/0.124	134/0.18	134/0.18	400/0.54	746/1	1500/2	3000/4	W/hp	
Cont. torque@tamb25°C	0.11/15,6	0.22/31.1	0.32/45.3	0.48/68	1.3/184.1	2.38/337.1	4.78/677	9.55/1352.4	Nm/oz-in.	Г
Peak torque@tamb25°C	0.32/45.3	0.62/87.8	0.9/127.5	1.59/225.2	3.8/538.13	6.8/963	14.3/2025	28.6/4050.1	Nm/oz-in	
Rotor inertia	0.075/0.0010	0.119/0.0017	0.17/0.0024	0.23/0.0033	0.34/0.0048	0.91/0.0129	6.26/0.0886	12.14/0.1719	kgcm <sup>2</sup> /oz-in-s <sup>2</sup>	Γ
Encoder resolution (standard)	4096	4096	4096	4096	8000/8192	8000	32767	32767	CPR	
Absolute Encoder (Single / Turns)					8192/4096	8192/4096	8192/4096	8192/4096	CPR/Rev	
Physical dimensions: MAC050-141 (dia x lenght) MAC400-3000 (wide x height x lenght)	Ø59x112/ 2.32x4.41	Ø59x131/ 2.32x5.16	Ø59x153/ 2.32x6.02	Ø59x172/ 2.32x6.77	60x114x191/ 2.36x4.48x7.52 with brake 60x114x224.5/ 2.36x4.48x8.84	80x115x175/ 3.15x4.53x6.89 with brake 80x115x207/ 3.15x4.53x8.15	130x200x182/ 5.12x7.87x7.16	130x200x232/ 5.12x7.87x9.13	mm/inch	
Weight without exp. module	0.6/1.32	0.85/1.87	1.1/2.43	1.33/2.93	2.3/5.1	3.5/7.72	6.5/14.33	10.5/23.15	kg/lb	
Protection class	IP42/IP67 optional				IP55 (IP66 on request)	IP55 (IP66 on request)	IP55 (IP66 on request)			
Flange	58.7x58.7/2.32x2.32				60x60/2.36x2.36	80x80/3.15x3.15	130x130/5.12x5.12		mm/inch	
Shaft	Ø6.35/0.25 (other diameter on request)				Ø14/0.55	Ø19/0.75	Ø24/0.95		mm/inch	



### JVL Industri Elektronik A/S

JVL Industri Elekronik A/S is a modern company, located in Birkerød, just north of Copenhagen. The up-to-date development, research and production facilities of JVL employ only the latest technology for the development and production of electronic controls for step- and servo motors. More than 50% of the staff are engineers with a very high degree of experience and competence in the field of motion control. We can therefore offer a product

JVL Industri Elektronik A/S Blokken 42 DK-3460 Birkerød, Denmark Tel: +45 4582 4440 Fax: +45 4582 5550 E-mail: jvl@jvl.dk www.jvl.dk

JVL Deutschland Tel: +49 711 51878564 Fax: +49 711 51878565 E-mail: jan.tausend@jvl.dk www.jvldrives.de









programme that includes all the necessary units and components to build up a complete motor control system.

JVL is represented throughout Europe and Asia by independent agents and in USA by a sister company, JVL International ApS. In Germany we have our own offices, JVL Deutschland. All distributors are carefully selected by JVL to have the necessary knowledge and experience to help our customers in the best possible way in their choice of motion control components.

> JVL USA & Canada JVL International Tel: +1 513 877 3134 Fax: +1 513 877 2471 E-mail:jvl@jvlusa.com www.jvlusa.com