





Conditions:

Supply voltage = See individual plot

Ambient temperature = 40°C

Torque setting = 100%

Load setting = 1.0

Operation above 3000 RPM can be done, but losses in the motor make it impossible to operate in this area continuously

— · — = Peak Torque

— = Average Torque