


MAC804 Torque versus speed



Conditions:

Supply nom. **115** or **230VAC** / 0 - 3000 RPM / @T.Amb. 0 - 40°C